

**Table 1: Rainier Commons Site Specific Sampling Results and Locations**

*(all results are preliminary)*

Building Owner	Building Number	Location Within Building	Matrix	Location ID	Sample Result	Sample Description
Tully's Coffee	1	Window Sill - First Floor	Paint	BN01PT01	4.30	peeling paint was collected from the window sill
	2	Main Hallway - First Floor Conference Room	Paint	BN02PT01	18.10	flaking paint was collected from the wall across the hall from a cubicle
	3	First Floor Bar - Wall at Entrance	Paint	BN03PT01	2.60	flaking paint collected from the wall
	4	First Floor Conference Room	Brick	BN04BR01	0.18	brick collected from the hallway between the east and the west conference rooms
		First Floor Conference Room	Paint	BN04PT01	7.70	paint collected from surface of a brick
	14	Main Storage Area	Plaster	BN14PL01	0.30	plaster collected from the north wall of the storage area
		Main Storage Area	Paint	BN14PT01	12.10	flaking paint collected from north wall
		Equipment Room	Paint	BN14PT02	29.80	paint sample collected
	24	First Floor	Paint	BN24PT01	5.02	paint sample collected from first floor
		Second Floor	Paint	BN24PT02	634.00	flaking paint sample collected from the top of the staircase to the second floor
	26	Lobby Area	Paint	BN26PT01	0.91	paint collected from the wall in the hallway
Groove Universe	7	Rehersal Room	Paint	BN07PT01	208.30	collected from the ceiling beam
Brew Masters	10	Entrance Hall of Residence	Plaster	BN10PL01	0.94	plaster sample collected near the remaining brick
		Living Room	Paint	BN10PT01	4.70	paint collected from the surface of the brick in the entrance hallway to the living room
		Stairwell	Paint	BN10PT02	8.40	flaking paint collected from the wall in the stairwell leading to the residence
Seattle Burlap	15	South Wall	Brick	BN15BR01	0.28	brick sample collected near the paint sample on the south wall
		South Wall	Paint	BN15PT01	17.10	collected on south wall
Sabaki Group	21	Floor 8R Living Room	Paint	BN21PT01	4.10	collected from the cailing in the sleeping quarters of the work/live loft.
		Floor 5R Office	Paint	BN21PT02	45.00	paint sample collected from the doorway above the office, this is the residence containing the small child
Nova Stone	22	Workshop	Paint	BN22PT01	20.50	collected from the column in the workshop near the bay door
Seitch 22		Floor 6R Living Room	Paint	BN22PT03	9.40	collected from the column near the entrance to the apartment
		6th Floor Stairwell Landing	Brick	BN22BR02	187.00	brick sample collected from the wall covered in green peeling paint
		6th Floor Stairwell Landing	Brick	BN22BR02D	370.00	duplicate brick sample collected from the wall covered in green peeling paint
		6th Floor Stairwell Landing	Paint	BN22PT02	17200.00	green paint sample from stairwell, colocated with brick sample BN22BR02
		6th Floor Stairwell Landing	Paint	BN22PT02D	22700.00	duplicate green paint sample from stairwell, colocated with brick sample BN22BR03